



MALLORY SONALERT PRODUCTS, INC.

Number: 17001

Date: 1/18/2017

### PRODUCT CHANGE NOTIFICATION

Reactions to this notification are to be addressed to Mallory Sonalert Sales Representative or Quality Control

**PRODUCT / MODEL CHANGE**

AST1240MLQ & AST1240MLTRQ

**CHANGE DESCRIPTION**

Sound hole is located on opposite side of part as compared to how it was previously packaged and reeled

**REASON FOR CHANGE**

New marking & reel assembly site

**CHANGE OF FIT / FORM / FUNCTION?**

N/A - No change to the operation of parts.

**DISPOSITION OF OLD PRODUCT**

Acceptable to use up current stock as is.

**ESTIMATED CODE DATE OF EFFECTED PRODUCT**

1603-1 (Jan 18, 2016)

**COMMENTS:**

NONE

**Approved By:** Dan Clark

**TITLE:** Quality Manager

**DATE:** January 18, 2017

**By:**

**TITLE:**

**DATE:**